

Tel: 847-526-6000 Fax: 847-438-6600 Toll-Free: 800-445-9970

Supplier Alert

11.22.19

Re: Un-incorporated changes to QC.4 Supplier Quality Manual

Dear Valued Supplier,

Please be aware of the current quality manual and ensure that the requirements are followed, which is for the general handling of our Aerospace designated products to contribute to product conformity. Specific requirements to a given product/part or order is flowed down through the customer supplied print and/or directions on the purchase order provider such as but not limited to; special requirements, critical items, and key characteristics, the need to use statistical techniques for product acceptance. Where suppliers are customer designated or approved for processing, it is required that their supplier supplemental purchase order conditions are met.

The latest version of AS9100D requires several new notification of supplier requirements and expected behavior of your personnel handling Morgan Bronze Products. Morgan Bronze is sharing these requirements as an un-incorporated change to QC.4 Rev. B Supplier Quality Manual for Aerospace providers and products until such time that the manual is updated in full to include any new elements. The supplier is fully responsible for ensuring that the organization as well as persons handling the product are aware of their contribution of product conformity and the requirement to meet print and order requirements. Their contribution to product safety when the part or feature is determined to be a safety critical, overall achievement of print specifications ensures product safety is met and the importance of integrity and ethical behavior.

While AS9100 is not a requirement to supply goods or services it is our hope that all suppliers will find it beneficial and rewarding to become certified to an international standard such as ISO9001, or NADCAP to improve your company's quality management system.

Best Regards,

Gabe Clark Cost Estimating Manager

Kyle Meinema Quality Improvement Manager

